

List of Mechanical Completed Works (2008 -2016)

S. No	Job	P.O. Number / Dated	Client	Completed
1	Re-galvanizing of Gratings and other steel method hot dip galvanizing at HUBCO Power Plant.	OM-3610 2 FEB, 2009	IPR	2009
2	Annual Inspection Boiler Unit # 1,2 3 & 4 Insulation, Cladding , Misc Mechanical Repair & Maintenance.	OM-1935	IPR	2010
3	Dismantling Fabrication Installation Blasting & painting of Boiler 4 Chequered Floor Plates at HUB Power Station.	OM-3606 28th Jan 2010	IPR	2010
4	Annual Inspection Boiler Unit # 1,2 3 & 4 Insulation, Misc Mechanical Repair & Maintenance.	OM-1935	IPR	2011
5	Repainting of Gis Duct & Support Structure & Removal & Refixing of Nuts, Bolts & washer of support structure of U#2.	OM-38495 19 th Sep 2011	IPR	2011
6	Internal Washing of RFO Tank No. 4 at HUB Power Station	OM-37238 12th April 2011	IPR	2011
7	Boiler duct and Bellows inspection and repairing work at unit No. 1. BQPTS	7500006328 5th Nov, 2010 FPO/G/5212/10/BQPS	KESC	2011
8	Services of steam coil air heater dismantling washing and assembling work at unit no.1 BQPS-1.	7500010237 DATED 04 -11- 2011	KESC	2011
9	Pressure parts Super Heater & Re Heater of Boiler at BQPS-1	7500006843 8/12/2010 FPO/G/5342/10/BQPS	KESC	2011
10	Services for Unit No. 6 water Washing of Boiler Pressure parts Super Heater & Re Heater of Boiler at BQPS-1	7500011117 29/12/2011	KESC	2011
11	Annual Inspection Boiler Unit # 1,2 3 & 4 Insulation, Cladding , Misc Mechanical Repair & Maintenance.	OM-1935	IPR	2012
12	Stack Steel Structure Repair & Reconstruction Unit no. 1 at HUB Power Station.	OM-42007 29th June, 2012	IPR	2012
13	Boiler duct and Bellows inspection and repairing work at unit No. 3. BQPTS	7500010395 14 Nov, 2011 FG5893/11BQ	KESC	2012
14	Services for Unit No. 1 water Washing of Boiler Pressure parts Super Heater & Re Heater of Boiler at BQPS-1	7500010234 4/11/2011	KESC	2012
15	Services for Unit No. 2 water Washing of Boiler Pressure parts Super Heater & Re Heater of Boiler at BQPS-1	7500015118 11/12/2012	KESC	2012
16	Services of steam coil air heater dismantling washing and assembling work at unit no.2 BQPS-1.	7500011250 Dated 12th Jan 2012 F/G/5919/11/BQ	KESC	2012
17	Services for Unit No. 1 water Washing of Boiler Pressure parts, Super Heater & Re Heater of Boiler at BQPS-1	7500010234 4/11/2011	KESC	2012

S. No	Job	P.O. Number / Dated	Client	Completed
18	Services for Unit No. 2 water Washing of Boiler Pressure parts, Super Heater & Re Heater of Boiler at BQPS-1	7500015118 11/12/2012	KESC	2012
19	Services of steam coil air heater dismantling washing and assembling work at unit no.6 BQPS-1.	7500011252 Dated 12th Jan 2012 F/G/5797/11/BQ	KESC	2012
20	Services of steam coil air heater dismantling washing and assembling work at unit no.5 BQPS-1.	7500014765 15th Nov 2012	KESC	2012
21	Services for Unit No. 2 water Washing of Boiler Pressure parts Super Heater & Re Heater of Boiler at BQPS-1	7500015118 11/12/2012	KESC	2012
22	Annual Inspection Boiler Unit # 1,2 3 & 4 Insulation, Cladding , Misc Mechanical Repair & Maintenance.	OM-1935	IPR	2013
23	services of steam coil air heater dismantling washing and assembling work at unit no.6 BQPS-1.	7500014766	KESC	2013
24	Epoxy paint for main start-up auxiliary transformers and insulated phase bus ducts at unit no 5 and 6 at BQPS-1	7500016195 DATED 20 -03- 2013	KESC	Apr-13
25	Refurbishment of oil distribution & storage scheme at TSW	7500016425 Dated 5th April 2013 REF NO.LPO/PP/66/2013	KESC	2013
26	Fabrication & Replacement of FDF-SAH Duct Portion on Boiler No. 4 at HUB Power Station.	OM-45188 5th August, 2013	IPR	2013
27	Hangers/Snubbers Replacement of Boiler No. 4 at HUB Power Station.	OM-45800 20th Sep, 2013	IPR	2013
28	Replacement of GAH rotor shell plates and radial Plates at HUB Power Station.	OM-1935 30th Oct, 2013	IPR	2013
29	Replacement of GAH Sliding Supports at HUB Power Station.	OM-1935 30th Oct, 2013	IPR	2013
30	Replacement of GAH Pin Rack Segments per side at HUB Power Station.	OM-1935 30th Oct, 2013	IPR	2013
31	Hangers/Snubbers Replacement of Boiler No. 2 at HUB Power Station.	OM-44470 15th May, 2013	IPR	2013
32	Annual Inspection Boiler Unit # 2 Insulation, Cladding , Misc Mechanical Repair & Maintenance.	OM-1935	IPR	2014
33	U2 R/H FSH Panels Replacement and Target Tube Replacement Project .	47784	IPR	2014
34	Boiler Performance Tests 2014 Unit # 1, Sampling Flanges at Hub Power Station	28166	IPR	2014

S. No	Job	P.O. Number / Dated	Client	Completed
36	Fabrication & Replacement of FDF-SAH Duct Portion on Boiler Unit # 1 at Hub Power Station	OM-48295	IPR	2014
37	Boiler Performance Tests 2014 Unit # 3, Sampling Flanges ECO Outlet Section at Hub Power Station	28167	IPR	2014
38	Boiler Performance Tests 2014 Unit # 3, Sampling Flanges GAH Outlet Section at Hub Power Station	28168	IPR	2014
39	Steam Drum Averaging Pipe Installation works Unit No. 1, at Hub Power Station.	PO # 49066	IPR	2014
40	Annual Inspection Boiler Unit # 1 Insulation, Cladding , Misc Mechanical Repair & Maintenance.	OM-1935	IPR	2014
41	Annual Inspection Boiler Unit # 4 Insulation, Cladding , Misc Mechanical Repair & Maintenance.	OM-1935	IPR	2014
42	Steam Drum Averaging Pipe Installation works Unit No. 1, at Hub Power Station.	PO # 47778	IPR	2014
43	Tank Internal Desludging & Wasdown including De-Greasing at Hub Power Station.	OM-49852	IPR	2014
44	Annual Inspection Boiler Unit # 3 Insulation, Cladding , Misc Mechanical Repair & Maintenance.	OM-1935	IPR	2014
45	Stack Rehabilitation Project.	OM-3936	IPR	2014
46	Steam Drum Averaging Pipe Installation works Unit No. 3, at Hub Power Station.	OM-1935	IPR	2014
47	Hangers/Snubbers Replacement of Boiler No. 3 at HUB Power Station.	OM-49870	IPR	2014
48	Boiler Superheater/ Reheater Tube Replacement Project at Hub Power Station.	PO # 50345	IPR	2014
49	Fabrication & Replacement of FDF- SAH Duct Portion on Boiler Unit # 3 at Hub Power Station.	OM-49871	IPR	2014
50	Support for the Stack Lining Project at Hub Power Station.	OM-49777	IPR	2014
51	Hangers/Snubbers Replacement of Boiler No. 1 at HUB Power Station.	OM-47833	IPR	2014
52	Replacement of GAH Rotor Shell & Sliding Feet	OM-51410 DATE 14th April, 2015	IPGDL	2015

S. No	Job	P.O. Number / Dated	Client	Completed
53	Fabrication & Replacement of FDF-SAH Duct Portion on Boiler-2	OM-51100 Date 13 March, 2015	IPGDL	2015
54	Tank Internal Desludging and Wash-down Services	51399 Date 1 April, 2015	IPGDL	2015
55	Replacement of Spring Hangers on Boiler-2	51504 Date 10 April, 2015	IPGDL	2015
56	Replacement of GAH Rotor Shell and Sliding Feet Cladding , Misc Mechanical Repair & Maintenance.	OM-51410 Date 14 April, 2015	IPGDL	2015
57	Boiler Forced Outage 2015 Unit -4 Manpower and Demobilization	S.O # 52127 Date 29 May, 2015	IPGDL	2015
58	Radial Seal Holding Strip for Gas Air Heater A & B at Hub Power Station	29690	IPGDL	2015
59	Replacement of GAH Rotor Sheel and Sliding Feet Unit No.3	OM-100374 Date 5 Nov,2015	THPCL	2015
60	Boiler Outages 2015; Forced Outages Unit 1, 2, 3 and 4. From January 2015 to December 2015	OM-1935	THPCL	2015
61	Annual Inspection & Maintenance of Boiler Unit 4	OM-1935	THPCL	2015
62	Annual Inspection & Maintenance of Boiler Unit 2	OM-1935	THPCL	2015
63	Annual Inspection & Maintenance of Boiler Unit 1	OM-1935	THPCL	2015
64	Annual Inspection & Maintenance of Boiler Unit 3	OM-1935	THPCL	2015
65	Radial Seal Holding Strip for Gas Air Heater A & B at Hub Power Station	101416	THPCL	2016
66	Annual Inspection & Maintenance of Boiler Unit 2	OM-1935	THPCL	2016
67	Annual Inspection & Maintenance of Boiler Unit 4	OM-1935	THPCL	2016
68	Boiler Outages 2016; Forced Outages Unit 1, 2, 3 and 4. From January 2016 to July 2016	OM-1935	THPCL	2016